


## Mufa PE100 redukcyjna (elektrooporowa)

ciśnienie PN16



średnica d x d1	L	A	A1	L1	L2	D	D1	Waga /g/
20 x 16	71	38	38	35	35	36	36	53
25 x 20	71	38	38	35	35	36	36	53
32 x 20	81	42	36	40	35	45	32	55
32 x 25	81	42	39	40	35	45	36	55
40 x 25	90	47	39	44	40	56	37	93
40 x 32	90	47	42	44	40	56	44	123
50 x 25	100	52	39	49	41	68	37	136
50 x 32	100	52	44	49	40	68	45	225
50 x 40	100	52	48	49	44	68	56	192
63 x 32	119	58	44	57	40	82	45	225
63 x 40	119	58	48	57	44	82	56	310
63 x 50	119	58	53	57	49	82	68	430
75 x 63	126	65	58	66	57	98	82	440
90 x 50	143	77	52	72	49	116	69	440
90 x 63	143	77	59	72	57	116	82	486
90 x 75	143	77	59	72	61	116	98	627
110 x 63	161	83	69	80	57	140	82	627
110 x 90	161	83	69	80	72	140	117	695
125 x 90	171	87	79	85	72	158	116	1019
125 x 110	171	87	69	85	78	158	116	1025
160 x 90	193	104	79	96	72	199	116	1440
160 x 110	193	104	87	96	81	199	141	1520
160 x 125	195	104	87	96	85	199	158	1570
180 x 125	212	114		105	85	222	158	2060