


Mufa PE100 PN10 (elektrooporowa)

ciśnienie PN10



średnica d	L	LI	D	A	Waga /g/
40	90	43	56	47	96
50	100	49	68	52	98
63	118	57	77	57	160
75	126	61	90	63	230
90	148	72	108	69	352
110	163	80	131	79	544
125	173	85	149	87	727
140	182	89	167	94	910
160	198	97	193	104	1350
180	212	104	215	114	1618
200	232	114	235	127	2100
225	240	118	264	141	2780
250	256	126	293	155	3728
280	275	135	332	166	5395
315	284	140	374	184	6802
355	280	138	421	204	8544
400	296	146	474	227	12000